DIGITAL READOUT MANUAL

MODEL : TECH-3i



Dear User:

Welcome to the use of TECH-3i DRO System, which is developed by Measurite Pte Ltd, the TECH-3i DRO System is widely used in milling machine, grinding machine, wire-cut, EDM and lathe, the functions can help us to improve efficiency, ease of operation, precise measurement and repeatability. It is now an absolute need to install them on your machine.

The Use of the DRO System, is easily understood by any user. You can use it without needing to finish reading the manual. You can use it very easily and is suitable for both new operator and skilled operator alike.

Safety precautions:

Open the box and remove it from the packing. Plug it with the power cable and test if the DRO powers up and the digit display correctly. It accepts power of 80Vac $^{\sim}$ 240Vac.

- When you open the box, check the physical appearance is in good condition, if you find something at fault, please contact the seller, be sure not to take dismantle it.
- (2) The DRO used the alternating current of $110V \sim 220V$ or $50Hz \sim 60Hz$, the electrical connector plugs pin is three core pin which has earth pin.
- ③ The user be sure not to repair it, the DRO has high-powered piezoelectricity, this could do some damage to people.
- ④ The chassis is made by ABS plastic, it can't be used in the high temperature.
- (5) When you do not use it, please turn off the electrical source. It can prolong the life-time of the product.

1

(6) If the thunder storm comes, close the electrical source.

Routine Maintenance:

- ① When you are cleaning the DRO , please turn off the power.
- ② Use a dry cloth or brush clean the keyboard / rear panel of the DRO.
- ③ Do not clean the panel or keyboard by thinner or ethanol.
- ④ The rear of the casing can be cleaned by detergent.

Promises:

If there are some issue with the DRO operation or the malfunctions, you can contact Measurite Pte Ltd at <u>www.measurite.com.sg</u> / email : info@measurite.com.sg

The Note of the Pressed key

TECH-31



Function project	4
Cleared	5
input Coordinate	5
INCH/MM	5
ABS/INC	7
1/2	8
RI	8
Calculator	9
SDM(300 Group)	9
Circle Hole	. 17
Ellipse Hole	. 21
Line Hole	. 25
Arc Hole	. 28
Smooth Arc	34
Slant	39
EDM	43
Basic parameters	45
Advanced Users	45
Trouble analyse and manage	47

List

TECH-3i DRO, used high-tech component and PCB assembly technique, more function, operate easily, credibility durable. Please read the manual before operation of the machines.

→ Function item 1、Cleared	X. Y. Z.
2. Input coordinate	⟨¬X ⟨¬Y ⟨¬Z
3、INCH/MM	IN MM
4、ABS/INC	ABS INC
5, 1/2	1/2
6、RI	RI
7. High user settings	9
8, Calculator	CAL
9、SDM	SDM
10、Circle-Hole	\oplus
11、Ellipse-Hole	\oplus
12、Line-Hole	⊥ ∕′
13, ARC-Hole	1 Alexandre
14. Smooth	AUTO R
15、Slant	
16, EDM	EDM

17, Power cut memory

, nine core bnc connector jack and sense organ connect table

Feet	1	2	3	4	5	6	7	8	9
size									
Func	null	0v	null	null	null	signal	5V	signal	RI signal
tion									





Operation steps



function: TECH-3i english prompt the dataview table provide two coordinate, they are ABS and INC.

1. The operator can memory the RI to ABS, and switch to INC for operationg.

2. Clear the INC coordinate at any place, the 1/2 can not affect the ABS coordinate.

3. at ABS coordinate the absolut value can autosave, and the operator can see it at any time.



Operation steps





Operation steps
make the X to another side \longrightarrow press $\frac{1}{2}$ \longrightarrow press \bigcirc X operate
RI \rightarrow press \overrightarrow{INC} \rightarrow move the machine tool to RI
1/2 midsplit autoly
Function: TECH-3i chinese prompt at currently data press $\frac{1}{2}$ and move the machine tool to Zero.
e.g: e set the X zero to the middle of the machine tool.
1, move the machine tool to one side , press X,
2, move the machine tool to another side, press $\frac{1}{2}$, and press
$\langle \mathbf{X} \rangle$
RI (Find RI)
Function: TECH-3i chinese prompt set the size of Zero and RI e.g: example for X
1. Clear the X at ABS, press X_0
2. press RI
3, move the machine tool when it come by the RI
When power off, if you move the operation table, you can find the RI by the RI function when you open it next time
Press $\mathbb{RI} \longrightarrow \mathbb{X}$, move the machine table when it come by RI, the
function window view and beep for "du-du".move the machine tool to "0.000".



Calculator

At everyday process, the most tool is calculator besides workpiece. The Calculator of the TECH-3i provide the function for add, minus, multiply, divide and some function , contains Sin , Cos, TAN.etc. The Calculator function can move the result to the axis which you need to operate it, the operator just need move the machine tool to zero.the place is you needed. 6×35=210 For example: 123+76=199 6 2 1 Press 3 5 6 attention: 1, if you input error press CE to cancel 2. when you finished press [X], the result move to X 3, at calculator press X move the data of X to calculator



TECH-3i chinese prompt the dataview table provide three coordinates:ABS, INC, SDM(SDM0-SDM299). 300 Group user coordinate can use to assistant zero in opeating.ABS is absolutent coordinate.it's established at the begin, it used to be the datum mark of processing workpiece.the SDM is defined relative to absolutent coordinate..

operation steps

like pic, the origin of the ABS is inthe centerof the workpiece, there are

two menthod to set.

① To place clear zero

② Coordinate input



4

 $\overline{\mathbf{O}}$

1

60

e.g 1: To place clear zero

set the workpiece zero to ABS zero.move the machine tool to SDM begin place and clear zero, when operating without reference to ABS or SDM, move the workpiece to "0.000".

Steps:

 Follow the methods of the midsplit autoly, set the ABS begin to the rectangle centre, AB neat to the X.

AD neat to Y, aim at O, ABS, X, Y clear near.

Sdm0 X, Y Clear Zero Sdm1 X, Y Clear Zero Sdm2 X, Y Clear Zero

Sdm3 X, Y Clear Zero





Operation Steps



(3) Set the first point SDM2 ,enter the SDM2 coordinate, Clear

12

0.000

0.000

0.000

() X

⇔ Y

♢ Ζ SDM multi-group

Total: 300

No. 3

Xo

Yo

Zo











Circumference be allotted a hole

Function: TECH-3i The obvious form of number provides the convenient circumference halving hole function . Person requires operation to import

The circumference radius

The circumference initiation angle

The circumference termination angle

The halving hole number



TECH-31 English is po	inted out
On the circumference t	he obvious form of number is calculated out
just voluntarily, ever	y divides the hole location from the middle ,
Every hole location is	set up for zero, Person needs operation press
III A	
or 🛄 , Which and	then the upper
hole choosing to the c	ircumference, the machine tool working table
is swaved to zero . i.	s the location being a hole's turn.
· · · ·	
Oper	ation Steps
eg. Radius: 30mm	
Initiation angle:30	
_	
End an angle: 318°	fring fring for a for the state of the state
Divide the hole num	ber
from the middle.	
TIOM THE MILLITE: 0	
	\vee
Operation Stone	
operation steps:	
anlit	ocation X=0,Y=0,press v enter the circle
\sim	
1 Sugar /]
\mathbb{N}	
	// v circle dispart
	Input Radius
Ψ	50.000 (> Y
	Zo
2. input the radius	(R: 30)
	ent
press 3 0	





which number holes queen to choosing , the machine tool working table being swayed arriving at is 0.000 Be the location owing a circumference a hole

- 2. Import process middle, Y Axis scintillation that can not stay, Pressent, That the number displays a form is able to enter next step voluntarily
- 3. If operation person requires that the halfway is temporary remove from "the circumference mark of hole " function, When returning to regular ABS state, X , Y , coordinate show, TAN

Press Withdraw from temporarily, Press return to circumference mark of hole state.



Ellipse be allotted a hole

Function: TECH-3i The god of the earth who points out that the obvious form of number provides the convenient ellipse halving hole function, handles person requires English to import an ellipse

X , Y axis radius Elliptic initiation angle

Elliptic termination angle

Elliptic maximal hole number



TECH-3i English mounts every halving hole location , every hole location is set up for zero to point out that the obvious form of number calculates out an ellipse just voluntarily, Person needs operation

Press 1 or 4 Which and then the upper hole choosing to the ellipse, the machine tool working table is swayed to zero, is the location being a hole's turn.

eg: X axis radius:20mm
Y axis radius: 30mm
Initiation angle: 0°
End an angle : 360°
The NO: 6
Operation Stone
operation steps
Attention:
1. The central point location is $X=0$, $Y=0$
2. The halving hole hole number is that the angle divides till
destination angle from starting maint along the 2 li
descination angle from starting point along the clockwise sense.
3. Think that the initiation angle is 00 , ending an angle is 360d
points, ought to be when importing the hole number $(N+1)$
Operation stops.
operation steps:
1. Fix position for zero first with workpiece centre location, then
press 🙀 enter the ellipse mark of hole function
eg. X. X. avis radius. — 20. 20mm
Cy. A. I AXIS LAULUS: 20, 30mm
Initiation angle: 30°
End an angle: $$ 360°
1 ne No: 6
La V Ellipse dispart
Input X Radius.
10.000 <> Y
Yo
Lo





Steps







Features: Chinese TECH-3i sub-slash provide tips for YX processing center in the same plane has been online, and uniform distribution of holes, the operator simply enter the following parameters slash length (first Kongyuan into our final hole center distance) slash angle

(referring to slash X-axis and the angle between the direction of) a few holes in the input parameters after a few tables will be automatically calculated slash the location of the hole, the operator according to \square choose holes, and then shaken to the workpiece X-axis is 0.000, 0.000 Y axis position is the location of the hole Example: For the diagram shows the workpiece, parameter setting is as follows Area Length: 150 mm Area angle: -300 Hole: 6 Steps: 1, turning tools at the first hole slash the first point, and then click to enter a slash--functional 0 Line Dispart (⊅ X Input Line length. Y 今 60.000 X, $\langle \mathcal{P} |$ Ζ Y. Z.



4, the importation of several slash-hole					
Deputy window display "Please enter the biggest hole," Y window					
display set up at the last few holes, followed by began					
processing $ \begin{array}{c c} 0.000 & \textcircled{>} X \\ \hline 0.000 & \textcircled{>} Y \\ \hline 0.000 & \textcircled{>} Y \\ \hline X_{o} \\ \hline X_{o} \\ \hline Z_{o} \\ \end{array} $					
5, by 🛈 or 🗸 outton, select the machining holes, and then shaker					
to the X-axis machine tool table, Y-axis display the "0.000" on the					
location of the points in the hole					
Note: The completion of processing 📛 to return to normal by the					
state showed that in the slash-hole course, the operator can					
TAN by the function returned to normal X X					
cemporarity reave the by the function returned to normal x, r,					
Z coordinates, and then return to the slash-TAN -functional.					



Arc processing

Features: TECH-3i Chinese few tips in simple arc processing system, a copper mold of single pieces, such as processing,

Universal Milling Machine can easily and quickly processed by the control of the same arc cutting each controlling a smooth arc, cutting of the less smooth processing of the arc, cutting the greater the volume, processing more rough arc, The shorter processing time.

A: processing XZ and YZ plane

Arc processing XZ and YZ have eight kinds of processing methods, as shown in Fig.



Can be used in the processing of flat-bottomed cutter or circular cutter processing in the use of flat-bottom arc, as a knife from the diameter b£ 0.000 B: XY plane processing In the XY plane processing, it is like eight processing, and processing of the vertical tool, and a way for each quarter Circular arc for the processing and processing; Therefore, in processing XY plane, it is necessary to choose knife compensation, processing XY plane, it is flat-ended knife or knives, according to the actual value set tools diameter. Arc processing parameters need to enter the following Processing of choice Select processing mode Inner / outer arc processing options (XY-specific) To be processed Radius Tool diameter Length of each processing Example 1: To processing as shown arc AB 900, from point A to start processing, the end point B, parameter settings are as follows: Processing side: XY R processing mode: 3 Processing of Arc Radius: 20 mm Tool diameter: 6 mm Feed: 0.5 mm Steps: 1, rocking machine worktable, turning tools at point A, X axis cleared 2, entered the arc processing U 20 Å R 50

Steps
$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$
Arc entered by processing
$\begin{array}{ c c c c c c c c c c c c c c c c c c c$
2 the processing of choice
4, followed by X ent elect XY plane into the selection process model
$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$
Note: XY plane by 🖓 X options
YZ plane by Choice
XZ plane by 🖓 Z choice (on the two-axis X-axis choice
XZ plane)







Note: In	the arc in	the process,	the opera	itor can te	emporaril	y leave
TAN						
the ,	R function	n returned to	normal X,	Y, X-axis	, then re	turn to
		TAN				
the arc ;	processing	function				



Smooth arc processing

Smooth arc processing to enter the following parameters Processing of choice Select processing mode Inner / outer smooth arc processing options (X, Y-specific) X, Y-axis coordinates of the location of origin Smooth radius to be processed Tool diameter Length of each step of processing Starting point of view End perspective

Example 1: machining surface: XY Processing of Arc X, Y-axis origin coordinates: (20, 30) Radius: 15 mm Tool diameter: 20 mm Stepping in: 6 mm Starting point of view: 00 The termination point of view: 3600 Smooth arc processing steps:

 rocking machine table, tool aimed at the smooth processing takes place starting point arc, each axis cleared.



Steps AUTO R to enter smooth arc processing functions. 2. bv SmoothR setup Х choosed plane: XY Y X, ⇔ Ζ Y. Z. The original settings plane 3, planar processing options, press 🖓 X or 🏷 Y keys to choose. 4, by 🖓 and then choose from within the arc arc processing or processing. SmoothR setup Х out doing Xo Y. Z٥ for the selection of Arc processing, according to 5, by arc processing. If you choose to face ZX, YZ plane, the within direct input of the coordinates of the origin location of the origin of the XY coordinates position refers to the processing smooth ard ent relative to the center position by-0.1 6, X axis coordinates input by ; input Y-axis coordinate value ent by







Steps



13, will show zero-axis machine tools. R which is the starting point for processing. By D display a processing point. Machine Tool Show

then moved to zero axis. Repeat operations to complete all processing is completed processing.



Slant processing

Features: TECH-3i Chinese few tips to provide a significant slope processing automatically calculate processing function, the operator can type the following parameters

Plane processing options (XY, YZ, for the slant processing XZ plane) Slant angle (in the XY plane and the X-axis slant that positive angle in the YZ plane with the Y-axis slant that positive angle)



Each processing slant length

After several significant input parameters Table hypotenuse will be automatically calculate the location of each point, the operator by

Example: processing as shown slant AB, parameter settings are as

follows Plane Processing: XZ Slant angle: 450	25 B 45° A
Each processing slant length:	1.2 mm

Steps

ſ

1, machine tool spindle tilt table 450, rocking machine processing
workstations at the slant-A start, the X-axis cleared, Z-axis
cleared. In the normal display by X_{\circ} Z_{\circ}
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
2, by processing functions will be inclined to enter parameter input, processing by the state directly to ent
ABS absolute $\begin{array}{c c} & & & \\ \hline \\ \hline$
The original settings plane processing









Note:

In the second step, if the X-axis no data (shown as 0.000), show support for the "EDM machining finished", can not be placed at the depth of need in the Z-axis EDM not cleared before entering, the Home a depth of the Z and then to operate.

EDM functions output wiring TECH-3I to provide a significant number of EDM specific features when the copper electrode has reached the depth of user settings,

TECH-3i digital display table in the relay switch signal will be issued, EDM machine will stop.

Connection of single-outputicon

TECH-3i digital display table back a DB9 socket, the socket is the TECH-3i digital output table EDM relay at the wiring. Wiring pin and methods are as follows:

(Yellow) (red) (black)



To process with the "closed" in place of "open" access: 2 and 3 feet (normally closed) to the process as "open" in place of "closure" to: 1 to 2 feet (normally open) often open to the general control. Note: the carton configuration of an output control. The basic parameter settings



2, And then the right of the LCD window will show "Password:

3、input Password

З

After entering advanced users based on user configuration requirements from the production home settings, users must not lose chaos on chaos, otherwise prevented normal use. Functional disorder caused by the software must be sent back to the manufacturers to set up, otherwise no warranty.

Setup parse

Press UP or DOWN

1, in the senior user settings, the LCD window on

ent tips enter resolution settings, and our digital form can be carried out separately for each axis resolution settings.

Steps

2, when entering resolution settings, the X, Y-axis show such as "0.00500." At this time by 🗘 X the X-axis display window flashes on $|\hat{U}|$ or $|\overline{V}|$ bond cycle choose a different resolution, and then the resolution of the current elected. Showing no window immediately, it means that the action has been completed. Note: If you would like to set up three-axis resolution, select a shaft after not directly by ent , but that on-demand changes in the resolution of several key axis of the home such as 4 Y 3, linear compensation Features: Chinese TECH-3i tips provide linear compensation, in accordance with the actual value of the processing and observation of the error between the value of compensation amendments. 4, restore factory settings. Show resumed factory settings, according to ent key Chinese Show: "Please wait initialization started......" and wait for a few seconds after the resumption of liquid crystal display "button on ENT restore settings," saying that this has been completed factory settings.

Fault Analysis and Processing

Fault	Analyze the causes	Approach
		1, power line inspection
		plug and socket
	1, missed good power	Interpolation is strong,
		whether good contact.
Do not show	2, a tributary of 110 V	2, inspection of a
	power supply voltage is	significant form of
	not within the scope of ~	insurance is good.
	220V	3, tests whether the input
		voltage 110 V ~ 220V range.
		1, machine tool bed with a
		few significant leader
1		Connectivity, and power
1		requirements of the earth
		The same.
		2, machine Chuangjiao such
		as plastic mats, the ground
	arounding bad	power supply must be linked
	r, grounding 200	to good ground, or else they
Chall Charged	2 220 V nower leakage	affect low-voltage power
Sherr charged		supply of sensors operating
		inconvenient.
		3.220 V power leakage, speed
	}	electrician requested
		formal inspection, there
		are still problems such as
		Please contact with the
		manufacturers of the
		manufacturers of the
		service.
		FireWire 380 V Dower 7000
		to avoid hurn a few
		aignificant nover or form
		factors of insecurity
		afforting the operatoria
		arrecting the operator s
		personal safety.
Axis showed a value	1, optical grating	recolution
of twice the normal	resolution settings	Lesoracion pottor
	incorrect	2, the factus pattern
	2, a set-axis diameter	aisplay settings
	display mode	

Fault	Analyze the causes	Approach
		1, a few tables in the
		power-down and then
		re-opened, a few
X, Y window	Table may be in power a	significant forms can be
display	few bad contact,	automatically scans of
confusion,	Affected by the power	their own-one.
numerical No	disruption	
laws,		2, if the first step is not
inaccurate		operating the trip, please
		refer to the specification
		of-way.
1		3, if the next step is still
		unable to rule out the
		possibility of the service
		please contact
		manufacturers
	1 grating foot table	
	with several similicant	
	approximate is good	
	contact is good.	
		Another axis grating and
multiple in the	2, no grating signal	see whether they can change
Table axis of a	output device.	their normal count, if
significant		transplanted to normal
number do not	3, check optical	after a device is the root
count	grating-foot body, feet	counting device
	first is the normal	malfunction. Customers are
	installation, whether	requested to speed the
	users limit themselves	above issues and service
	demolished, rendering	companies associated with
	the first reading by	the Department.
	ultra-foot trip Penghuai	
	body.	
	4. a few tables in the	
	axis counting problems	

	1, machine tool accuracy	1, maintenance or transfer
	Guide bad.	Machine Tool Guide is
		space.
	2, machine tool running	
	too fast.	2, reducing the speed.
Table count		
several	3, sub-grating device	3, reload grating feet
significant	installation	firmly ministries to
errors that	requirements of the	install on Connecting
distance and	parallel device did not	Plate.
the actual	adjust well, whether on	
distance	Connecting Plate	4, set the correct
inconsistent	ministries firmly	resolution.
	installed.	
		5, set the correct value of
	4, the grating set foot	the linear error
	resolution inconsistent	compensation.
	with the actual	
	resolution.	6, repair or replacement of
		optical grating.
	5, linear error	
	compensation value is	
	not set up correctly.	
	6, grating bad feet, and	
	missed a few.	

